| | Well taged: AAF 233 | |
|---|--|--|
| File Original and First Copy with Department of Ecology Second Copy — Owner's Copy Third Copy — Driller's Copy 30/3E/05/K STATE OF W | LL REPORT Application No Application No Application No | |
| | Address Rt. 4 Box 1209 Camanols, Wish, 90292 | |
| (2) LOCATION OF WELL: County Island | | |
| Bearing and distance from section or subdivision corner 1096 We ar | | |
| (3) PROPOSED USE: Domestic Municipal [| (10) WELL LOG: | |
| Irrigation Test Well Other | Formation: Describe by color, character, size of material and structure, show thickness of agulfers and the kind and nature of the material in e | |
| (4) TYPE OF WORK: Owner's number of well NA | stratum penetrated, with at least one entry for each change of format MATERIAL FROM TO | |
| Old Hom well Method: Dug D Bored | | |
| Reconditioned Calabara Rotary Jetted | Mel drilled and cased instruct | |
| (5) DIMENSIONS: 1. V Diameter of which inches. | Could never get any into | |
| Drilled 158 ft. Depth of completed well 158 ft. | him or possiable drill record. | |
| (6) CONSTRUCTION DETAILS: | | |
| Casing installed: 6 "Diam. from Top n. to 56 n. | | |
| Threaded () "Diam. from ft. to ft. Welded () "Diam. from ft. to ft. | 10 1964 Water 1265. | |
| Perforations: Yes No 🗆 | bolow top of casing | |
| Type of perforator used NO + MTOOP | | |
| SIZE of perforations. Hat known in by in in perforations from the to ft. | A. 1965 Water 132 + | |
| Perforations from ft. to ft. to ft. | below top of caring | |
| 1 | | |
| Screens: Yes No Ot Pump intake | Spot 917 wither 1368+ | |
| Type Model No | | |
| Diam. Slot size from ft. to ft. | - pelon top of carine | |
| Gravel packed: Yes No Size of gravel: | | |
| Gravel placed from ft. to ft. | US. G.S. has store | |
| Surface seal: Yes No To wind Depth? | | |
| Material used in seal Did any strata contain unusable water? Yes Ho | into. They may have | |
| Type of water. Depth of strate Method of sealing strata off | carler into. | |
| (7) PUMP: Manufacturer's Name Myers | | |
| Type: Sub Merse. H.P. 3/4 | CRECEIVED | |
| (8) WATER LEVELS: Land-surface elevation Apple: 110 manufacte level Apple: | APR 0 1 2008 | |
| Artesian pressure NA lbs. per square inch Date | DEPT OF ECOLOGY | |
| Artesian water is controlled by (Cap. valve, etc.) | | |
| Drawdown is amount water level is | Work started | |
| Was a numb test made? Yes No If yes, by whom? | WELL DRILLER'S STATEMENT: | |
| Yield: 12 gal./min with ft. drawdown after 2 hrs. | This well was drilled under my jurisdiction and this repo | |
| 9 9 9 | true to the best of my knowledge and belief. | |
| Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level) Time Water Level Time Water Level Time Water Level | NAME Miller (Initials not kind (Person, firm, or corporation) (Type or print) | |
| 30 Sec. | Address Deg d | |
| | | |
| Bailer test MA gal/min, with ft. drawdown after hre. | [Signed] (Well Driller) | |
| Arterian flow | License No Date | |
| No take /a/e) charged callforms erg. | | |
| Water Soft no tron, slight calcions. | | |

| <u> </u> | 30/03-05R |
|---|---|
| File Original and First Copy with Department of Ecology Second Copy — Owner's Copy Third Copy — Driller's Copy 30/35/05/ E STATE OF W | LL REPORT |
| (1) OWNER: Name Saratoga Vista Water Assn. | Address Rt. 4 Box 1209 Camanols, Wash, 98292 |
| (2) LOCATION OF WELL: County Island | _SE 1/4 Sec 5 T30 N, R3E WM |
| Bearing and distance from section or subdivision corner 1096 W. Ar | id 275 N. SECON, Sec. S'(Existing) |
| (3) PROPOSED USE: Domestic F Industrial Municipal | (10) WELL LOG: |
| Irrigation Test Well Other | Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each |
| (4) TYPE OF WORK: Owner's number of well NA | stratum penetrated, with at least one entry for each change of formation. MATERIAL FROM TO |
| Method: Dug | |
| Reconditioned C CASER Rotary Detted D | Well drilled and cased insport |
| (5) DIMENSIONS: 1. Diameter of Casing 6 inches. | mid-1928 by one Mr. Miller |
| Drilled 158 ft. Depth of completed well 158 ft. | Lin or possiable drill records |
| | THE DE POSSIGN E CONTRACTOR |
| (6) CONSTRUCTION DETAILS: Casing installed: | |
| Threaded" Diam. from ft. to ft. | |
| Welded Diam. from ft. to ft. | July 1964 Water 1265. |
| Perforations: Yes No D | below top of casing |
| Type of perforation used Not known in. by in. | |
| perforations from | Aug 1965 Water 132 + |
| perforations from ft. to ft. | pelow top of casing |
| | |
| Screens: Yes No Ct Pump in Ake | Spot 947 wither 1368+ |
| Type Model No | |
| Diam. Slot size from ft. to ft. Diam. Slot size from ft. to ft. | - below top of casing |
| Gravel packed: Yes No Size of gravel: | |
| Gravel placed from | |
| Surface seal: Yes No Towns Ochth? of the M. | U.S. G.S. has above |
| Material used in seal | info. They may have |
| Did any strata contain unusable water? Yes Depth of strate | 1075 They 11147 The |
| Method of sealing strata of | carlier into |
| (7) PUMP: Manufacturer's Name Myers | D. C. D. |
| Type: Sub merse, HP 3/4 | |
| (8) WATER LEVELS: Land-surface elevation Approx 110 | 1 |
| Static level See The top of well by Artesian pressure Lbs. per square inch Date | |
| Artesian water is controlled by (Cap, valve, etc.) | |
| | |
| (9) WELL TESTS: Drawdown is amount water level is lowered below static level Was a pump test made? Yes No I if yes, by whom? | Work started 19 Completed 19 |
| Yield: 2 gal./min. with ft. drawdown after hrs. | WELL DRILLER'S STATEMENT: |
| | This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief. |
| Passwery data (time taken as zero when pump turned off) (water level | Mill (Initials not known |
| measured from well top to water level) Time Water Level Time Water Level Time Water Level | (Person, firm, or corporation) (Type or print) |
| 20 500 | Address Dega |

Date of test 1017 1904

Bailer test 11 A gal/min with ft. drawdown after hrs.

Artesian flow g.p.m. Date

Temperature of water 5 6 1 Was a chemical analysis made? Yes No Date

No tobe (0/6) showed colliform org.

No tobe (5 10 limit) slight calcion, (USE ADDITIONAL SHEETS IF NECESSARY)

S.F. No. 7356—OS (Rev. 4-71)